BID OPENING CERTIFICATION RECORD

Date of	Bid Walk: <i>3/15</i> ,	/18 Due Date: 3	/22/18 HNS#:	18-38		
		Address	:	РВ	E Amount	
PUBLIC	BODY ESTIMATE	4015 FIELD	CREST RO.	_30,	461	
PUBLIC	BODY ESTIMATE:					
PUBLIC	BODY ESTIMATE:			• This had a marke		
PUBLIC	BODY ESTIMATE:					
PUBLIC	BODY ESTIMATE:	12/00/0				
			ATTENDEE	S		
51	GMA	·			, 100 profit file (14) . 100	
<u></u> 800	NMAN					
<u>So</u>	00616					
				BID	DERS	
	Address:		SIGMA	ROWMAN	Goodill	
		20	38,880			
1.	4015 416	UDCREST KILL	38/880	21,225	33,564	
2.						
3.						•
4.						
5.						
				ened and read aloud	n the Neighborhood &	Business Services
Office lo	cated at 600 E. Trad	de Street, Sharlotte, I	icl		0 /-	
Bids Ope	ened By: U.M. M	Alton Dones	Bids Reco	orded By: Kind	ustra	
Witness	ed By:		Bids Reco	MARCH 22	,2018	
Note:	Responsive bids ar	e those which fall wit		ove and 15% below th	ne public body cost esti	mate. As a



CITY OF CHARLOTTE
NEIGHBORHOOD & BUSINESS SERVICES

Company Acknowledgement:

The undersigned, having become thoroughly familiar with the terms, conditions, limitations, and provisions of the housing improvement work to be performed at 4015 Fieldcrest Rd. to be funded through the City of Charlotte Neighborhood & Business Services, in addition, having fully inspected the site in all particulars, hereby proposes and agrees to fully perform the work within the time stated and in strict accordance with the proposed contract documents including furnishing of any and all labor and materials, and to do all work required to complete said Work in accordance with the advised respective contractual, for the sum of money:

All labor, materials, services and equipment necessary for the completion of the Work shown on the Drawings and in the Specifications:

on the Drawings and in the Specifications:

THIRTY THREE HOUSAND FIVE HUNDRED & SIXY SEVEND Dollars (\$ 33,567)

Written total

Specs Dated: 2/22/18 Number of Pages: 10 pages

Addenda # 1 Dated: Number of Pages:

Addenda # 2 Dated: Number of Pages:

Project Schedule: Minimum Start Date - 5/7/18

Completion Deadline: 6/8/18

Please Print and Sign:		
Company Name/Firm:	Goodwill	THOUSTILES AZ SP
Authorized Representativ	ve Name: 13な	AN OTTO, DURGETOR
Signature:	Mello	Date: 3/21/2018



CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

Requirements For Bidders

The City awards rehabilitation bids to the lowest responsive and responsible bidder. A responsible bidder for the safe home program is one who:

- 1) Is a licensed general contractor in the State of North Carolina;
- 2) Has an Renovate, Repair & Paint Certification (http://www2.epa.gov/lead/renovation-repair-and-painting-program);
- 3) Is not listed on a local, state or federal debarment list;
- 4) Carries an appropriate amounts of insurance;
- 5) Can provide references verifying the contractor has completed work of a similar scope in a good workmanship like manner or successfully completed prior work for the Safe Home program. Referenced work must have been completed in one year or less from date of this invitation to bid.

A responsive bidder must:

- 1) Submit all requested documentation on time;
- 2) Meet the above requirements for responsibility at the time of bid submittal;
- 3) Have the capacity to meet the required schedule for the project.
- 4) Existing rehab projects contracted by the contractor must be on schedule.

The City reserves the right to waive any minor informalities or irregularities, which do not go to the heart of the bid submittal or prejudice other offers, or to reject, for good and compelling reasons, any or all bid submittals.

Mikel Taylor Rehabilitation Specialist City of Charlotte Neighborhood and Business Services 600 E. Trade St.

Charlotte, NC 29202 PH: (704) 336-4115 Fax: (704) 632-8575



CITY OF CHARLOTTE
NEIGHBORHOOD & BUSINESS SERVICES

Instructions to Bidders

Explanations to Bidders

Any explanation desired by a Contractor regarding the meaning or interpretation of the advertisement for bids, drawings, specifications, etc., must be requested in writing to the Rehabilitation Specialist with sufficient time allowed for a reply to each Contractor before the submission of their bids. Any interpretation made will be in the form of an addendum to the invitation for bids, drawings, specifications, etc., and will be furnished to all prospective Contractors. The Contractor must acknowledge any revision to the bid documents in the space provided on the bid form and it must be submitted with their bid package.

Preparation of Bids

Bids shall be submitted on the forms furnished, or copies thereof, and must be manually signed. If erasures or other changes appear on the forms, the person signing the bids must initial each erasure or change

- The Contractor's Bid Proposal must be properly executed and submitted on the form provided. Bids by Contractors must be received by the Rehabilitation Specialist at the time and place specified on the "Invitation to Bid"
- No bid will be considered unless all individual work items on the Bid Form including any addendums are priced. The sum of all work items must equal to the Total Bid Amount.
- Unless called for, alternate bids will not be considered
- Modification of bids already submitted will be considered if received at the office designated in the invitation for bids by the time set for opening of bids

Submittal of Bids

- Sealed bids will be submitted to the Safe Home Program Office as directed in the invitation to bid prior to or at the appointed bid opening time
- Bld will be time stamped on the date of delivery
- Each bid must be submitted in a sealed envelope bearing on the outside the name of the Contractor, the name of the project for which the bid is submitted, and the date and time of the bid opening
- All bids submitted must be typed or written in ink and signed by the Contractor's designated representative

G:\SELECTIVE REHAB TEAM\forms\bid forms and documents\Invitation to bid WARREN



CITY OF CHARLOTTE

- NEIGHBORHOOD & BUSINESS SERVICES
- Failure to include all forms may result in rejection of a bid
- Required Bid Package Forms:
 - o Scope of Work
 - o Addenda Acknowledgement
 - o Itemized Work Sheet
 - o Subcontractor Certifications (if applicable)

NEIGHBORHOOD & BUSINESS SERVICES

http://housing.charlottenc.gov | 600 E. Trade Street | Charlotte, NC

2

3

Response Due: 2/22/2018 11:15 am

Prepared By: City of Charlotte Housing & Neighborhood Services 600 E. Trade Street Charlotte, NC 28202 (704) 336-7600

Property Details	e de la companya del companya de la companya del companya de la co	entraformation to accommode their	n e erske et mast w	2 14 c 4 1 14 4 1			
Address:	4015 Fieldcrest Rd	Owi	ner:				
	Charlotte, NC 28210	Owi	ner Phone:	,,			
Structure Type:	Single Unit	Pro	gram(s):		gency Repa		
quare Feet:	1144			Safe	Home FY 2	018	
/ear Built;	1960						
roperty Value:	65500						
ax Parcel:	14521511						
Census Tract:							
roperty Zone:	Council District 3						
Repairs	and a series of the series of						
Description	ender in mengens i gemengalah Semis, padaparan sebahagan di bahasan padaparan sebahan kesasan			Floor	Room		Exterio
Permits Required							
	sponsible obtaining and paying for a	ll permits required. Sa	ıld permits :	shall Ind	clude all Iter	ns in th	ls scope of work.
		Bld Cost;	700	х	1	=	700
		DIG 00311	Base	` <u>~</u>	Quantity		Total Cost
Portable Tollet	ering committee with the merid of the delight of the surface first believed to the surface of th						
Provide temporary t	oilet facilities from job start until app	roval of permanent fa	cilities.				
		Bld Cost:	200	X	1	=	200
			Base		Quantity	,	Total Cost
Trash Removal	\$ 186 St. 98's an access of the second secon	g bladerer gebie en begen mediene i i meditet konstationel	- 18 - 19 - 19 - 19 - 19 - 19 - 19 - 19				
After procuring all re	equired permits, place AS MANY rol ontrol methods. Remove dumpster a ımp trallers.	l-off dumpsters as ne nd repair any evidend	eded wilhou e of the du	ut dama mpstera	iging the sit s use, Contr	e, Colle ractor n	et construction nay haul debris
		Bld Cost: _	351	Х	1	=	351
	•		Base		Quantity		Total Cost
	to the second se						
							1251

	Bld Cost: _	1875	_x_		=	1875
		Base		Quantity		Total Cost
Exterminate insects		1370 111.17 (11026.4)	121 11 2.4.	General l	•	
Exterminate for insects. Include a one year wa	nranty. All extermination shall b	e performed	by a	licensed con	tracto	or.
	Bld Cost; _	550	_x_	_/	. =_	220
ድርስ በመጣሊያ ዘገባል ኤ. ፊኒ መዲስ የመጣሚያስ ከተለማ የሚያስ ነው ላይ የሚያስ ማስማ ነገር ነው።		Base	LT17' 0' 'T	Quantity		Total Cost
Bath Exhaust Fan Replace	2.000			Bathroot	n	
Install a ceiling mounted, vent fan with dampe	r vented to the outside. Repair	any tear out	•			
	Bld Cost: _	450	_x_	1	<u>=</u> _	450
	_	Base		Quantity		Total Cost
GFCI Device Exterior			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Exterior	.,	
Install two surfaced mounted ground fault circle front door and the other shall be accessible from	uit interrupt receptacles in a we om the deck.	ather proof	cover	lo code. One	e oull	et shall be near t
	Bid Cost: _	5W	Х	1	=	500
	2/4 00411	Base		Quantity		Total Cost
Smoke Detector Hard Wired	فالثانية واستخدمته بمثاني والمتاهد والمتاهدة والمتاهدة والمتاهدة والمتاهدة والمتاهدة والمتاهدة والمتاهدة والمتاهدة	and the second seco		Hall and	Bedi	rooms
Install UL approved, Interconnected, celling m battery backups in bedrooms and outside of s		ors permane	ntly w	ired into a re	cepta	icle boxes with
DETECTOR IN HALL SHALL BE A COMBINA	ATION CO/SMOKE DETECTO	R،				-
	Bld Cost: _	750	X		=	750
		Base		Quantity		Total Cost
	A Paris 2, 18 % by party and any separate and paris 1,000 and 1,000 and any section 2, graphs as			Living R	loom	and Bedrooms
Convert 2 Prong Outlets to 3 Prong		akers on the	circui	its servicing i	these outlets	outlets. Install as required by
	prong outlets, Install GFCI bre servicing bedroom outlets, Inst	all new cove	rplate	0 4114 144 01 0		
Convert 2 Prong Outlets to 3 Prong Replace existing two prong outlets with three combination GFCI/AFCI breakers on circuits s	prong outlets, Install GFC) bre servicing bedroom outlets. Inst Bid Cost;	all new cove	orpiate	ĵ	_=_	1200
Convert 2 Prong Outlets to 3 Prong Replace existing two prong outlets with three combination GFCI/AFCI breakers on circuits s	servicing bedroom outlets. Inst	1 200 Base	rplate X_	Quantity		
Convert 2 Prong Outlets to 3 Prong Replace existing two prong outlets with three combination GFCI/AFCI breakers on circuits s	servicing bedroom outlets. Inst	iall new cove	x_	Î	, 15 . 5 . 5 .	1 200 Total Cost

	Bld Cost; _	650	x	1	Ħ	650
	D(0 003(,	Base		Quantity	-,	Total Cost
Rewire Dryer Cord	is ing namen and also and the angles of the		,_p_ + + + + + + + + + + + + + + + + + +	Laundry		and at a contactor and
Install a cord clamp and cover plate over the cord conne	ction to the dryer.					
	Bid Cost: _	75	_x	1	<u> </u>	75
		Base		Quantity		Total Cost
Remove Garbage Disposal	ishin dipenungan yenduntung terang me	egyster filt gifte tig this is magained.	************	Kitchen	,	
Remove garbage disposal and dispose of properly. Rep	olumb sink into drain	llnes, Termin	nate wi	re in a juncil	on bo	х.
	Bld Cost:	100	X.	1	=	.100
		Base		Quantity		Total Cost
Dishwasher	ەۋەسىلىنىدېسىۋېرۋەشىد شەۋەتۇشىنىدۇدۇنىۋە ۋەر بى ۋ	· · · · · · · · · · · · · · · · · · ·		Kitchen		
Install a 2-cycle dishwasher that is EnergyStar rated. O	wner's choice of cold	or,				
•	Bld Cost;	BUN	Х	l	=	600
	· · · · ·	Base		Quantity		Total Cost
Replace Range	· · · · ·			Quantity Kitchen	*** *****	Total Cost
Replace Range Remove existing range and dispose of properly.	· · · · ·				111 may 7 phon	Total Cost
Replace Range		Base	be app	Kitchen	e reha	b specialist befo
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing ele	octric range, Brand a	Base		Kitchen	reha	
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing ele	octric range, Brand a	Base nd model to 700 Base	x_	Kitchen broved by the Quantity	# 	b specialist befo
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing elementary installation. Color choice by owner.	octric range, Brand a	Base nd model to 700 Base	x_	Kitchen proved by the	iii	b specialist befo
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing ele	octric range, Brand a	nd model to	XX	Kitchen broved by the Quantity Kitchen	to action to	b specialist befo
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing elements installation. Color choice by owner. Cabinet Repair	ectric range, Brand a Bid Cost: _ wood bottom, Finish	Hase 700 Base with white s	XX	Kitchen broved by the Quantity Kitchen	to action to	b specialist befo
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing elements installation. Color choice by owner. Cabinet Repair	octric range, Brand a	Hase 700 Base with white s	XX	Kitchen broved by the Quantity Kitchen	palni	b specialist befo
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing electric installation. Color choice by owner. Cabinet Repair Repair base cabinet under kitchen sink by installing ply	ectric range, Brand a Bid Cost: _ wood bottom, Finish	Base 700 Base with white s	XX	Kitchen oroved by the Quantity Kitchen oss low-VOC	D pain	b specialist before the special state of the specia
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing electric installation. Color choice by owner. Cabinet Repair Repair base cabinet under kitchen sink by installing ply Replace Missing/Broken Drawers Replace existing drawer bank cabinet in kitchen with new	Bld Cost: _ wood bottom. Finish Bld Cost: _	Hase 700 Base With white s 250 Base	X eml-gl X existir	Kitchen Quantity Kitchen Quantity Kitchen Quantity Kitchen g as close a	D pain	to specialist before the special state of the speci
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing electric installation. Color choice by owner. Cabinet Repair Repair base cabinet under kitchen sink by installing ply	Bld Cost: _ wood bottom. Finish Bld Cost: _	Hase 700 Base With white s 250 Base	X eml-gl X existir	Kitchen Quantity Kitchen Quantity Kitchen Quantity Kitchen g as close a	D pain	to specialist before the special state of the speci
Replace Range Remove existing range and dispose of properly. Provide and install a new 4 burner 30" free standing electric installation. Color choice by owner. Cabinet Repair Repair base cabinet under kitchen sink by installing ply Replace Missing/Broken Drawers Replace existing drawer bank cabinet in kitchen with new Replace one other missing drawer in kitchen base cab	Bld Cost: _ wood bottom. Finish Bld Cost: _	Base 700 Base With white s 250 Base net to match missing drav	X eml-gl X existir	Kitchen Quantity Kitchen Quantity Kitchen Quantity Kitchen g as close a	D pain	to specialist before the special state of the speci

Double Bowl Sink Complete Install a 18 gauge 33" x 22" x 9" double bowl, stainless steel, self rimml rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-trap, sur on all supply & drain lines. No copper compression fittings. Bid Co Replace Tub/Shower Valve and Trim Remove the existing tub and shower valve and trim and replace with ne Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	ost:	Base Plumble OVE TUE	X X Cluding ball ty X X S S S S S S S S S S S	Quantity Kitchen I a single hape shut-off Quantity Bathroo de and the C	2,10) In the second of the se	Total Cost metal body fauce & escutcheon process Total Cost uction Standards MATERIALS. the wall surface
Double Bowl Sink Complete Install a 18 gauge 33" x 22" x 9" double bowl, stainless steel, self rimml rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-trap, sur on all supply & drain lines. No copper compression fittings. Bid Co Replace Tub/Shower Valve and Trim Remove the existing tub and shower valve and trim and replace with ne Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	ng kitche pply lines pst: www.per.th OT REM k side of	en sink inc., full port Base e Plumbli OVE TUE	X Ag Cocas SUR	Kitchen I a single hape shut-off Quantity Bathroode and the C	ondle revalves	Total Cost metal body fauce & escutcheon p 6.50 Total Cost uollon Standards MATERIALS. the wall surface
Double Bowl Sink Complete Install a 18 gauge 33" x 22" x 9" double bowl, stainless steel, self rimml rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-trap, sur on all supply & drain lines. No copper compression fittings. Bid Co Replace Tub/Shower Valve and Trim Remove the existing tub and shower valve and trim and replace with ne Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	ng kitche pply lines pst: www.per.th OT REM k side of	en sink inc., full port Base e Plumbli OVE TUE	X Ag Cocas SUR	Kitchen I a single hape shut-off Quantity Bathroode and the C	ondle revalves	Total Cost uction Standards MATERIALS. the wall surface
Double Bowl Sink Complete Install a 18 gauge 33" x 22" x 9" double bowl, stainless steel, self rimml rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-trap, sur on all supply & drain lines, No copper compression fittings. Bid Co Replace Tub/Shower Valve and Trim Remove the existing tub and shower valve and trim and replace with ne Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	oply lines ost: ow per th OT REM k side of	Base Base Plumbli OVE TUE	X ng Coo	Quantity Bathroode and the C ROUND FIN pathy and (Ig	ondle revalves	Total Cost uction Standards MATERIALS. the wall surface
rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-trap, sup on all supply & drain lines. No copper compression fittings. Bid Co Replace Tub/Shower Valve and Trim Remove the existing tub and shower valve and trim and replace with new Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	oply lines ost: ow per th OT REM k side of	Base Base Plumbli OVE TUE	X ng Coo	Quantity Bathroo de and the C ROUND FIN eatly and tig	om Constru VISH M	Total Cost uction Standards MATERIALS. the wall surface
Replace Tub/Shower Valve and Trim Remove the existing tub and shower valve and trim and replace with ne Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	ow per th OT REM k side of	Base e Plumble OVE TUE	S SURI	Bathroode and the CROUND FINeally and (Ig	Constr NISH M htly to	Total Cost uction Standards MATERIALS. the wall surface
Replace Tub/Shower Valve and Trim Remove the existing tub and shower valve and trim and replace with ne Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	ow per th OT REM k side of	Base e Plumble OVE TUE	S SURI	Bathroode and the CROUND FINeally and (Ig	Constr NISH M htly to	uction Standards MATERIALS. o the wall surface
Replace Tub/Shower Valve and Trim Remove the existing tub and shower valve and trim and replace with ne Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	OT REM k side of	OVE TUE	S SURI	de and the C ROUND FINeatly and (Ig	Constr NISH M htly to	MATERIALS. • the wall surface / 4 v ^y
Access to the valve will be through the back side of the tub wall. DO No Scope includes the installation of a removable access panel on the back	OT REM k side of	OVE TUE	S SURI	ROUND FINeatly and (Ig	NSH M	MATERIALS. • the wall surface / 4 v ^y
Scope includes the installation of a removable access panel on the bac	k side of	the wall I	o fit ne	eatly and tig	hily to	the wall surface
Scope includes the installation of a removable access panel on the bac	k side of	the wall I	o fit ne	eatly and tig	hily to	the wall surface
•				1	_=_	1400
Bid Co	st:	Base	_x_		_=_	
	n di seeder di se seen	Base		Ougastitus		
				шиапппу		Total Cost
Grab Bars				Bathroo	m	
Install three 1 1/2" diameter S/S Grab Bars at owner's choice of location pounds), (38.1)	ns (inclu	de wood	blockir	ng In wall. E	ach b	ar must hold 300
Bid Co	et;	300	X	1	=	300
		Base		Quantity		Total Cost
Prep & Paint Room Semi Gloss		· · · · · · · · · · · · · · · · · · ·	-4	Bathroo	ını	and the second seco
Remove or cover hardware and accessories not to be painted. Scrape fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new with owner's choice of low VOC acrylic SEMI-GLOSS latex. Painting st hardware, fixtures and accessories. Any moving of furniture required shardware.	v malerk nall inclu	als and sp de walls a	ot prir	ne existing v	with a	crylle latex. Top o
Bld G	ost:	400	_x_		=	400
		Base		Quantity		Total Cost
						.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
						3550
						-
		•				
		•				
Work Specification - City of Charlotte Housing & Neighborhood Service						2/22/2018

9.1/	
1/2	

Vinyl Plank Flooring

Bathroom 805

Remove existing layers of floor coverings to subfloor. Install 1/4" underlayment.

Install 25 year warrantled resillent floor covering per manufacturer's specifications, include transitions and painted or stained wood quarter-round at all perimeters to complete installation.

SHEET VINYL SHALL NOT BE USED.

New resilient floor covering shall be equivalent or better quality than Allure PLANK & TILE series manufactured by TrafflcMASTER or similar product with a minimum thickness of 3.8 mm. Resilient flooring shall have a 25 year warranty.

If repairs to the subfloor or floor framing are required, a change order will be issued.

Work Specification - City of Charlotte Housing & Neighborhood Services

NOTE: FLOOR VENT SHALL BE RELOCATED TO A LOCATION ACCEPTABLE TO THE HVAC SUB AND THE REHAB

	Bld Cost:	700 x	/ =	700
•	, , , , , , , , , , , , , , , , , , ,	Base	Quantity	Total Co
Commode Replace 1.6 GPF			Bathroom	and desired from 1874 has a second amount from
nstall a new commode shall be complete with seat, se ype, free-standing close-coupled closet combination, v i 1,6 gallon water-saver as required by the North Caro Mansfield, or Kohler brands. Color shall be white.	itrecus china complyit	ng with U.S. Cor	nmercial Standard	CS20-63, and
	Bld Cost:	465 x	<i> </i>	46
	Dia Ovar, _			······································
		Base	Quantity	Total Co
avatory Faucet	ap, supply lines, full po	ल्लाक स्थापनाक च्या तथा वस्तु । स्वस्तु के स	Bathroom	
••••	ap, supply lines, full po	ल्लाक स्थापनाक च्या तथा वस्तु । स्वस्तु के स	Bathroom	
avatory Faucet Replace wilh new melal faucet, drain with pop-up, p-tra	ap, supply lines, full po Bid Cost: _	ल्लाक स्थापनाक च्या तथा वस्तु । स्वस्तु के स	Bathroom	
avatory Faucet Replace wilh new melal faucet, drain with pop-up, p-tra		ल्लाक स्थापनाक च्या तथा वस्तु । स्वस्तु के स	Bathroom	utcheon plates
avatory Faucet Replace with new metal faucet, drain with pop-up, p-tra supply and drain lines.		ort ball type shut	Bathroom -off valves and esci	utcheon plates 3 85 Total C
avatory Faucet Replace wilh new melal faucet, drain with pop-up, p-tra	Bld Cost:	ort ball type shut	Bathroom -off valves and esci	utcheon plates 3 85 Total C
avatory Faucet Replace with new metal faucet, drain with pop-up, p-trasupply and drain lines. Adjust/Trim-interior Door	Bld Cost:	ort ball type shut	Bathroom -off valves and esci	utcheon plates 3 85 Total C

	BLE. Bld Cost:	250	x	1	= 25
	nia 00s(, _	Base		Quantity	Total
Slab Door Interior	цина и до на вирования учения и подделжения обществория	ajo uso ammo e glimustania a programa, e programa	********	Hall	- ac - apa ampurasimus nunnum amijet
Install a slab door to existing jamb, mortise in hinges a bedrooms and bathroom, passage for all others. Mate			, Includ	e new hard	ware. Locking t
PAINT DOOR TO MATCH EXISTING.					
DO NOT INSTALL A DOOR STOP.					
	Bld Cost:	250	X	1	_ 23
•	_	Base		Quantity	Total
Prep & Paint Room Flat			,	Living Ro	om
Remove or cover hardware and accessories not to be fungus, dirt, and dust from surfaces. Repair holes an	d cracks. Prime all new	materials and	i spot p	rime existir	ng with acrylic is
coat with owner's choice of low VOC acrylic FLAT late furniture required shall be included.					
coat with owner's choice of low VOC acrylic FLAT late	i trim shall be painted w	vith semigloss			
coat with owner's choice of low VOC acrylic FLAT late furniture required shall be included.	i trim shall be painted w Bid Cost: _	vith semigloss	x	ĺ	× 8

Vinyl Plank Flooiring

Entire House

A

Remove existing carpet, pad, and tack strip throughout house and dispose of properly. Remove existing shoe mold in kitchen and dining area.

Install 25 year warrantied resilient floor covering per manufacturer's specifications, include transitions and painted or stained wood quarter-round at all perimeters to complete installation,

SHEET VINYL SHALL NOT BE USED.

New resilient floor covering shall be equivalent or better quality than Allure PLANK & TILE series manufactured by TrafficMASTER or similar product with a minimum thickness of 3.8 mm. Resilient flooring shall have a 25 year warranty.

If repairs to the subfloor or floor framing are required, a change order will be issued,

Install new paint shoe mold throughout.

NOTE: THIS ITEM INCLUDES VINYL PLANK IN THE KITCHEN AND LAUNDRY AREA. THE BATHROOM IS INSTALLED UNDER A SEPARATE LINE ITEM.

		Bld Cost: _	7923 x	1	Ħ	7923
			Base	Quantity		Total Cost
	Install Squirrel Proof Screen at Gable Vents		2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Attic		amount of the section
30	Install heavy duty 1/2" hardware cloth on the attic side of the vents.	e gable vents. Se	eourely fasten ever	y 3" Inches a	round	the perimeter of the
		Bld Cost: _	315 x	ĺ	=	315
			Base	Quantity		Total Cost
_	Attic Insulation Increase to R-38	· · · · · · · · · · · · · · · · · · ·		Attic	********	A combined to a select manifest of the State
31	Increase attle insulation to R-38, contractor to attach verific code.	ation to rafter at a	illo access, easily	seen. Include	e vent	lation baffles to
		Bld Cost: _	1055 x		_=	1055
			Base	Quantity		Total Cost
	والمراوع والمراوية المراوية في مستقد ليسترون والمراوية و					

9293

40 Gallon Gas Water Heater

Building Systems

32

Remove existing water heater and all obsolete or deteriorated flue piping and gas line and dispose of properly.

Install an insulated 40 gallon, glass lined, high recovery gas water heater with a 10 year warranty and an Energy Factor of .61 or greater.

Installation includes PRV valve and extension, drain pan with drain to the exterior, expansion tank, and new gas line and flue piping through the roof as necessary to meet the requirements of the Construction Specifications and Code.

		Bld Cost:	1900	х	1 =	1900
			Base		Quantity	Total Co
Vapor Barrier	generals in a model, in region of the investment of the model and the control of the second	gage ang ti Shamad e ang tigit dan 190 til shamad 190 menadamban pambanas member			Crawl Space	C6
Lay 6 mil poly vapo	or barrier on ground in crawl spa	ice and 6" up foundation w	alis, Overlap	веап	ns by 2' and sec	cure with duct tap
NOTE: REMOVE	ALL DEBRIS FROM CRAWL B	EFORE INSTALLING POL	Υ,			
		Bld Cost: _	350	х	/ =	. 53
			Base		Quantity	Total Co
Reset Existing Ex	derlor Door	and the second s	*		Kitchen	
an air tight seal of	ioor and reinstall square, plumb, door against weatherstripping, atween door assembly and hous	Repair framing and subfloo	between do or under doo	or an r as n	d frame all the v acessary to ins	way around. Esta tall door correctly
		Bld Cost: _	500	х_	1 .	500
		_	Base		Quantity	Total Co
Repair Storm Do		and it is not become a factory of the contribution of the state of section of the state of the s			Back Door	•
Replace latch on r	ear storm door.					
		Bld Cost;	55	_x_		= 55
	no o todo de terror dos proposados de la composição de la		Base		Quantity	Total Co
Reset Existing E					Living Roc	om
an air tight seal of	loor and reinstall square, plumb door against weatherstripping. stween door assembly and hous	Repair framing and subfloo	o between do or under doo	ooran ras n	d frame all the ecessary to ins	way around. Est stall door correctly
		Bld Cost; _	SW	х	1.	500
			Base		Quantity	Total Co
	g Deck and Bulld New	nine verezione, in egit idea (NA Arriva, Arriva en 11 septembre)	me ikke attisch besicklich bilde		Deck	ika delekaran yang dapan beranggal delekal bagi
Demolish the exist handralls, Comply	ting deck and dispose of all deb with State Code and Construct	ris properly. Bulld new 8' x on Specifications	t 10' deck co	mplet	e with guardrali	ls and steps with
		Bld Cost: _	2500) x_		2500
			Base		Quantity	Total Co
	before the transfer and the forest transfer and the second				** ** **** ******	
Work Specification	1 - City of Charlotte Housing & N	leighborhood Services				2/22/2018

	Bld Cost; _	309	_x_		P	3,00
	0 (11 VIII 124 (11))	Base		Quantity		Total C
≅xterlor Handralis				Front Po	rch	
Remove existing handralis. Dispose of properly. Re-l	nstall pressure treated h	andralis me	eling a	all requireme	nts of	the Bulldin
NSTALL GRAB RAIL ON THE SIDE OF EACH RAIL	. AT A HEIGHT THAT IS	COMFORT	[ABLE	FOR THE H	OME	OWNER.
	Bld Cost:	800) _x	Í	<u>.</u>	A O
		Base		Quantity		Total (
Exterior Handralis	promings for the control of the state of the Control of the state of t	La grant, ou p any, any, and, a	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	mend gottaments and see	the state of the	sakem daya sakes
nstall pressure treated handralls meeting all requiren	nents of the Building Co	de at the ste	ps fro	m the sidewa	alk to	the drivews
NSTALL GRAB RAIL ON THE SIDE OF EACH RAIL	. AT A HEIGHT THAT IS	COMFORT	rable	FOR THE H	OME	OWNER.
	Bld Cost: _	550.°°	y X	1	Ħ	53
	Dia 0001, _	Base	``	Quantity		Total
Panair Cracks in Veneer						
				Exterior		
	d right side of house and	I neally rese		Exterior		9/5
		I neally rese		Exterior	_=_	
Remove old sealer from cracks in veneer on front and	d right side of house and Bid Cost; _	I neally rese		Exterior oks. (Quantity	1	
Remove old sealer from cracks in veneer on front and	d right side of house and Bid Cost;	I neally rese		Exterior oks.	3	
Repair Cracks in Veneer Remove old sealer from cracks in veneer on front and an acceptance of the contract of	d right side of house and Bid Cost;	a neatly rese		Exterior oks. (Quantity	tal .	
Remove old sealer from cracks in veneer on front and	d right side of house and Bid Cost;	a neatly rese		Exterior oks. (Quantity Exterior		Total
Remove old sealer from cracks in veneer on front and Reset Foundation Vents Reset All foundation vents and resecure all loose ve	d right side of house and Bid Cost: // ents, Bid Cost:	2.50 Base		Exterior oks. Quantity Exterior Quantity		Total
Remove old sealer from cracks in veneer on front and Reset Foundation Vents Inspect all foundation vents and resecure all loose vents all loose ve	Bld Cost;	2.50 Base	xx	Exterior oks. (Quantity Exterior	i i	Total
Remove old sealer from cracks in veneer on front and Reset Foundation Vents nspect all foundation vents and resecure all loose vents all loose	d right side of house and Bid Cost; onts. Bid Cost; at the front right corner of	Base How the house	x X	Exterior oks. Quantity Exterior Quantity	in the second se	Total
Remove old sealer from cracks in veneer on front and Reset Foundation Vents nspect all foundation vents and resecure all loose vents all loo	Bld Cost;	Base How the house	x X	Exterior oks. Quantity Exterior Quantity Exterior	-	Total
Reset Foundation Vents Inspect all foundation vents and resecure all loose ve	at the front right corner of	Base HS Base U Base	X X	Exterior oks. Quantity Exterior Quantity Exterior Quantity Cuantity	E	Total Grant
Remove old sealer from cracks in veneer on front and Reset Foundation Vents Inspect all foundation vents and resecure all loose vents all loos	Bld Cost: onle, Bld Cost: at the front right corner of	Base HS Base U Base	X X	Exterior oks. Quantity Exterior Quantity Exterior Quantity Exterior	E	Total
Remove old sealer from cracks in veneer on front and Reset Foundation Vents Inspect all foundation vents and resecure all loose vents all	at the front right corner of Bid Cost;	Base HS Base U Base re treated 2:	X X	Exterior oks. Quantity Exterior Quantity Exterior Quantity Exterior	E	Total
Remove old sealer from cracks in veneer on front and Reset Foundation Vents Inspect all foundation vents and resecure all loose vents all loos	at the front right corner of Bid Cost;	Base House Hou	X X	Exterior oks. Quantity Exterior Quantity Exterior Quantity Exterior	E	Total Total Total
Remove old sealer from cracks in veneer on front and Reset Foundation Vents Inspect all foundation vents and resecure all loose vents all	at the front right corner of Bid Cost;	Base House Hou	X X	Exterior oks. Quantity Exterior Quantity Exterior Quantity Exterior	E	Total Total Total

45	Fill Hole in Yard						Site			
. (,	Shovel excess dirt int	o hole in back yard.	act every few inc	ery few Inches. Rake and seed and straw area.						
				Bld Cost: _	75	х_	1	H	75	
	a na ang ag manapanan na banapan ang tengga pang ang ag manapanan na pang at na banapan banapa pang m Banapang manapanan na banapan ang tengga pang pang ang manapan pang ang manapan pang pang pang pang pang pang				Base		Quantity		Total Cost	_
	Certification				•	osti Li			75	
	Contractor Name:	(pol)wi	il thousa	THES OF	SP		Total (Cost; _	33,567	
	Signature;	150 l	A Ally	5			Date:	3	122/2018	